

INSTALLATION INSTRUCTIONS


Surface Mount Kit for LED Flat Panel 2x2 , 2x4

Please read and understand this entire manual before attempting to assemble, operate or install the product.




WARNING: Avoid fire or electric shock. Follow Installation Instructions carefully. If unsure about electrical installation, consult a qualified electrician. Wear rubber-soled shoes and work on a sturdy wooden ladder. Ground fixture to avoid potential electric shock. Handle metal parts carefully to prevent cuts. To avoid a hazard to children, account for all parts and destroy all packing materials.

CAUTION: Turn off the power at fuse or circuit breaker box before installation and maintenance. Fixture must be installed according to National Electric Code and local building codes. If you are unsure about wiring, consult a qualified electrician.



Installation



1. Find the installation location, and place the position board to the ceiling.
2. According to the position board, install 2 parallel frame bars (with holes) to the ceiling.
3. Buckle the corner code into the non-hole frame (until the button is fully popped).
4. Put the broadside of one side of the holeless border (with corner code) facing down, align the border with the cardboard edge (to expose 4 small ears), and put the remaining 4 ceiling screws on.
5. Thread the wire through a metal hose with one side bend (through the bend side).
6. Pry open the hole on the side of the junction box on the lamp body, open the junction box cover, and then operate in the space below the junction box cover to pull out the power cable inside the junction box from hole position. Pull out the cable and put back the junction box cover.
7. Slide the lamp body from the non-power end into the ceiling frame.
8. Connection.
9. After connecting the wire, plug the excess wire back into the junction box, and then tie the metal hose connector into the hole in the junction box.
10. Cover the last side of the ceiling frame (broadside down) and the installation is complete.